A Department of Army both westbound lanes Civilian was killed in an and entered the grassy accident July 15 at 1210 median sideways. local in Ft Hunter Liggett, The vehicle then Calif. The DAC was rolled and ejected the Preliminary LOSS REPORTS operating a Caterpillar Soldier as it crossed road grader clearing the eastbound lanes. a firebreak when the He was not wearing Caterpillar slid backwards his seat belt. The for the week of 13-19 JULY 06 down a drop-off. The Soldier had completed impact ejected the an ASMIS-2 risk DAC through the rear

not wearing a seatbelt.

glass of the cab. He

was pronounced dead

at the scene. He was

A Soldier was killed in a single vehicle accident July 16 at 0542 local near Ft Stockton, Texas. The Soldier was returning to Ft Bliss, Texas, from leave in Enterprise, Ala. While driving his 2003 GMC Yukon, he fell asleep and the vehicle drifted off the right side of the road. After over-correcting to the left, he lost control of the vehicle, crossed

assessment for this trip.

► A Soldier was killed in a motorcycle accident July 16 at 1330 local in Fayetteville, N.C. The Soldier was operating a 2006 Suzuki M50 when he ran a red light at a controlled intersection. A 2005 Hyundai Santa Fe, making a left turn, crossed into the path of the Soldier's motorcycle resulting in a collision. The Soldier was taken to a local medical center where he died as a result of his injuries. He was wearing a DOT approved half-helmet,

https://crc.army.mil

had attended the Armyapproved Motorcycle Safety Foundation Course seven years ago and had completed the Commander's Safety Course last year.

A Soldier was injured in a motorcycle accident July 16 at 1500 local near

Heidelberg, Germany. The Soldier was operating his motorcycle in a group ride when his motorcycle collided with other motorcycles in the group.

gun truck in a convoy escorting third country nationals. The Soldier's vehicle was the second vehicle in a three-vehicle convoy. As the second vehicle approached the main gate of a forward operating base, the third vehicle did not stop and impacted the second vehicle. The impact caused the second vehicle to push forward and impact the lead gun truck causing both to roll.

A Soldier was injured in a multi-Army motor vehicle accident July 18 at 0520 local in Iraq. The Soldier was the gunner of an up-armored ASV







U.S. SOLDIERS/CIVILIANS

DIED IN

ACCIDENTS

 2 Soldiers injured • 1 Road Grader Destroyed

• 2 Gun Trucks Damaged